5473/USSN 09/839,407 Group Art Unit 1731

Respectfully submitted,

CAROL LEFEBVRE DU GROSRIEZ ET AL

Βv

Mary J. Breiner, Attorney Registration No. 33,161 115 North Henry Street P.O. Box 19290 Alexandria, Virginia 22320-0290

Telephone (703) 684-6885

Attachments - Marked-Up Version of Specification - Formal Drawings (7 sheets, Figures 1-15)

## MARKED-UP VERSION OF SPECIFICATION

Replace the paragraph at page 10, lines 23-25 with the rewritten paragraph as follows:

"FIGURE 6D is a schematic partly cross-sectional view of the first engraved cylinder applied against the second, hard, smooth engraved cylinder along line [VI-VI] 6D-6D of FIGURE 6,"

Replace the paragraph at page 10, lines 28-30 with the rewritten paragraph as follows:

"FIGURE 7A is a schematic and part cross-sectional view of the first engraved cylinder applied against the second hard cylinder along line [VII-VII] 7A-7A of FIGURE 7,"

Replace the paragraph at page 10, lines 34-36 with the rewritten paragraph as follows:

"FIGURE 9A is a schematic part cross-sectional view of the first engraved cylinder applied against the second hard cylinder along the line [IX-IX] <u>9A-9A</u> of FIGURE 9,"

Replace the paragraph at page 11, lines 2-4 with the rewritten paragraph as follows:

5473/USSN 09/839,407 Group Art Unit 1731

"FIGURE 10A is a schematic partial cross-section of the first engraved cylinder applied against the second engraved hard cylinder along line [X-X] 10A-10A of FIGURE 10,"

Replace the paragraph at page 11, lines 7-9 with the rewritten paragraph as follows:

"FIGURES 11A-11D are schematics of partial cross-sections of the first engraved cylinder applied against the second engraved cylinder along line [XI-XI] 11A-11A of FIGURE 11,"

Replace the paragraph at page 19, lines 22-29 with the rewritten paragraph as follows:

"The heights h'<sub>1</sub> and h'<sub>2</sub> of the salient parts of the engraved zones 3004 and 3005 of the first engraved cylinder 3001 and the heights h'<sub>3</sub> and h'<sub>4</sub> of the salient part of the second hard cylinder 4001 are shown in FIGURE 9A which, in a partial cross-section along the line [IX-IX] <u>9A-9A</u> of FIGURE 9, represents the configuration of the first engraved cylinder 3001 and the second hard cylinder 4001 compressed against each other during the marking stage."